

Inspection Order No. :

BOSS No. : Page No.:

1 of 10

Date of issue:

Dec 15, 2015

declared):

INSPECTION REPORT

(non-negotiable)

- Description and Quantity of Commodity(as per PI

Galvanized steel pipe / 1500pcs

- Name & Address Of Seller:

- Name & Address Of Buyer:

RELIANCE METAL RESOURCE CO.,LTD

Hi-Tech Building C, #909, Nankai District Tianjin, China

- Inspection Date & Place:

Dec 15th, 2015, Tianjin city, China;

- Packing list No .:

PL744.

Date: Dec, 9th, 2015

-Performa Invoice:

20151110744 Date: Nov 10th, 2015

- Nature Of Inspection:

Item

Comment

Quantity check Packing check randomly

Acceptable with note Acceptable

Marking check randomly Visual quality check randomly Dimension check randomly

Acceptable Acceptable Acceptable

Zinc thickness check Loading supervision

Acceptable Acceptable

Gross weight check

Subjected to buyer's evaluation

- Inspector:

Jimmy Zhao

Jimmy Zhao

- Reviewed by

Willow Liu

This is to report that we, SGS-CSTC Tianjin Branch at the request of [RELIANCE METAL RESOURCE CO., LTD]conducted the following inspection:

Disclaimer

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS-CSTC Standards Technical Services (Tianjin) Co., Ltd. Industrial Service

[V: 00 Nov.2012]

No.555, Central Avenue, Airport Economic Area, Tian China, 300345

t: +86(0)22-59803788 f +86(0)22-59803766 www.cn.sgs.com Member of the SGS Group (Société Générale de Surveillance)



Instrument checklist

During the inspection, the following instrument calibration status has been checked for inspection:

Inner equipment

N.I.	MEASURING INSTRUMENT DESCRIPTION	CALIBRATION	CERTIFICATE NO.
No.	(Including measuring range and equipment No.)	STATUS	(OPTIONAL)
1	Steel tape (IND-TJ-JC20m-12)	EFFECTIVELY	EFFECTIVELY
2	Vernier caliper (IND-TJ-KC-17)	EFFECTIVELY	EFFECTIVELY
3	Micrometer (IND-TJ-WJ-03)	EFFECTIVELY	EFFECTIVELY
4	Paint film thickness gauge(IND-TJ-TC-05)	EFFECTIVELY	EFFECTIVELY

Inspection Finding:

1. Quantity Check:

Reference documents:

→ Packing list: PL744,

Date: Dec, 9th, 2015

Method of quantity check

→ Quantity check by bundles totally and inner pieces check randomly.

→ Sample size: ANSI/ASQ Z1.4-2008 S-4, according to actually bundles, total 17 bundles.

The cargos were storage in warehouse when SGS inspector arrived at inspection location, quantity check was performed by SGS inspector as per packing list provided by client, actual finding as follow table:

100	Ite Galvanized steel pipe (mm)	Sample	Bundle quantity		Inner quantity		Total quantity (pcs)	
		size (bundle s)	Req. quantity (bundle s)	Act. quantity (bundle s)	Req. Quantity/bun dle (pcs)	Act. Quantity/bu ndle (pcs)	Req quantity	Act. quantity
4	00 45 5000	204 55200	N/A	8	N/A	61	500	500
1	60x4.5x5800	2	N/A	1	N/A	12		
2	48.3x4.0x580 0	2	N/A	11	N/A	91	1000	1001

Note: for size 48.3x4.0x5800 total 1001 pcs which is 1 piece more than the required quantity.

Result: The result of quantity check was acceptable with above note.

2. Packing check

Sample size:

→ ANSI/ASQ Z1.4-2008 L-II, according to actually bundles, total 6 bundles.

Reference documents:

→ Performa Invoice: 20151110744, Date: Nov 10th, 2015

Packing check was performed by SGS inspector randomly, actual finding were as below:

✓ The pipes were packed in bundles and fastened by galvanized steel strips at 4 different portions (3 steel strips at both bundle ends, 2 steel stripes at body of the bundle).

Page 2 of

✓ No other packing was found, such as waterproof cloth, lifting belt etc.

Inspection Order No.:



Result: The result of packing check was acceptable due to no specific requirements from client.

- 3. Marking check
- Sample size:
 - → ANSI/ASQ Z1.4-2008 L-II, according to actually pieces, totals 130pcs.
- Reference documents:
 - → Performa Invoice: 20151110744, Date: Nov 10th, 2015

No marking was found on pipe body during the inspection.

Result:

• The result of marking check was acceptable due to no specific requirements form client.

Inspection Order No.:





4. Dimension check:

- Sample size:
 - → ANSI/ASQ Z1.4-2008 S-4, according to actually pieces, total 33 pieces.
- Reference documents:
 - → Performa Invoice: 20151110744, Date: Nov 10th, 2015

During the inspection, dimension check was performed randomly by SGS inspector, the selected pipes were marked by SGS inspector with No.1~No.33. Actual finding were as follow table:

Item	Specification (mm)	Sample size (quantity/samples)	Outer diameter Pipe ends (mm)	Wall thickness (mm)	Length (mm)
	Acceptable 7	Tolerance	±0.3	±0.2	±20
1	60x4.5x5800	500pcs / 13pcs	60.0~60.2	4.4~4.5	5805~5810
2	48.3x4.0x5800	1000pcs / 20pcs	48.3~48.4	4.0~4.1	5805~5810

Note:

- 1. The dimension check was performed on the pipes which were necessary and available, according to practical situation on site due to supplier did not open the packing.
- 2. The length of the pipe was measured from one side end to another end along the pipe body with steel tape.
- 3. Four measured points were selected randomly for thickness check at pipe ends with micrometer.
- Two measured points were selected randomly for outer diameter check at pipe ends with vernier caliper.

Result:

The result of dimension check was acceptable according to requirements of Performa Invoice.

5. Visual Quality Check:

- Sample size:
 - → ANSI/ASQ Z1.4-2008 L-II, according to actually pieces, totals 130pcs.
- Reference documents:
 - → Performa Invoice: 20151110744, Date: Nov 10th, 2015

During the inspection, visual quality check was performed randomly by SGS inspector. Actual finding were as below:

- a) The pipes were silvery color and plain ends.
- b) An internal visible weld seam was found on every inspected pipe.
- c) No other visible defects, such as damage, crack, deformation, etc. were found during the inspection.

Result

The result of visual check was acceptable due to no other specific requirements from client.

6. Zinc thickness check:

- Sample size
 - → ANSI/ASQ Z1.4-2008 S-4, according to actually pieces, total 33 pieces.
- Reference documents:
 - → Performa Invoice: 20151110744, Date: Nov 10th, 2015

Inspection Order No.:





During the inspection, Zinc thickness check was performed randomly for the pipes by SGS inspector.

Actual finding were as follow table:

Item	Specification (mm)	Sample size (quantity/samples)	Zinc thickness (um)
	Acceptable T	olerance	≥30.8um
1	60x4.5x5800	500pcs / 13pcs	36.9~69.5
2	48.3x4.0x5800	1000pcs / 20pcs	34.8~57.1

Note:

- 1. The Zinc thickness was checked by paint film thickness gauge.
- 2. The tolerance of Zinc thickness was calculate by 220g/m²

Result:

The result of Zinc thickness check was acceptable according to requirements of Performa Invoice.

7. Loading supervision:

The above commodities were stuffed into 2x20FT containers under SGS supervision as following

No.	Container No.	Size.	Shipping Co. Seal No.	SGS Seal No.	Quantity of bundles
1	CMAU1196192	22G1	D8363216	B3493373	10
2	ECMU1868371	22G1	D8363212	B3394621	10

Remark:

 The result of loading supervision was subject to the client's evaluation as no detail requirements was provided.

8. Gross weight check:

SGS inspector witnessed weight check process and actual finding as below table:

Truck No.	Empty weight (kg)	Filled with goods (kg)	Gross weight (kg)
1	17060	59930	42870
		Total	42870

Remark:

The supplier/manufacturer did not submit the calibration certificate of weighbridge.
 so the above weight value was just for reference and SGS inspector can not verify the
 actual weight value.

Result:

. The result of gross weight check was subjected to buyer's evaluation due to above comments

In accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

Inspection Order No.:

[V: 00 Nov.2012]

Page 5 of 10



This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

THIS REPORT ONLY REFLECTED OUR ACTUAL FINDINGS. THE INSPECTION WAS DONE TO THE BEST OF OUR KNOWLEDGE AND ABILITY AND WITH DUE CARE. THE FINDINGS ARE VALID AS FOR TIME AND PLACE OF INSPECTION.





Inspection Order No.:




Inspection Order No.:





Inspection Order No.:






Inspection Order No.:

Gross weight check







End of report

FOR AND ON BEHALF OF SGS-CSTC STANDARDS TECHNICAL SERVICES CO., LTD.



Inspection Order No.:

Page 10 of 10